
## Turbocharger


## Troubleshooting Guidelines



Carbon build-up







bearing surfaces. To avoid damage, oil and filters should be of a quality recommended by the engine manufacturer. These should be changed when a new turbocharger is fitted and at regular intervals according to the

- Malfunctioning oil filter by-pass valve
- Degraded lubrication oil.

Failure from excessive exhaust temperatures or hot shutdown of engine results in carbon build-up. It is recommended that you idle the engine for two to three minutes to cool the bearing system before shutting down. Turbine end heat soak into the bearing housing results in oil carbonisation and corrosion of the bearing system. The main damage occurs to the shaft seal ring and grooves, turbine end bearing and bearing housing oil drain cavity blockage.

Carbon build-up can be caused by:

Hot shutdown of engine

lubricating oil.

- Degraded oil quality carbonising in service
- Infrequent oil change intervals causing oil breakdown in service
- Air and gas leaks
- Faulty fuel injector pump/injectors.

Before changing your turbocharger, please make sure that you have correctly identified the cause of the fault.

## **Excess smoke Engine lacks power** Noisy/Whistling Seized/Sluggish Worn/Excessive clearance Often the noise comes from air/gas Caused by: Caused by: If the turbocharger rotor assembly Dirty air cleaner Dirty air cleaner leakage due to pre-turbine exhaust has seized or is tight to rotate,

- Air intake system restriction Cracked mounting flange/gasket
- Fuel pump/injectors/valve timing
- incorrectly set Wastegate mechanism set
- incorrectly
- Turbocharger damaged.
- Air intake system restriction • Cracked mounting flange/gasket
- Exhaust for foreign object restriction
- Fuel pump/injectors/valve timing incorrectly set
- Burnt valves and/or pistons Turbocharger damaged.

gas or air/boost leaks. Check all joints. If noise continues,

check turbocharger clearances and

wheels for housing contact.

this is often due to lubricating oil degregation, which can cause a high build up of carbon in the bearing housing interior, restricting rotation. Insufficient or an intermittent drop in oil pressure can cause the rotor to

seize, as can introducing dirt into the

A turbocharger has specific axial and radial rotor clearances. These are sometimes mis-diagnosed as 'worn bearings' (See engine manual or nearest authorised Holset distributor). If the clearances are out of specification the cause could be attributed to a lubricating oil problem, i.e. insufficient oil, dirt ingress, oil contamination with

Remember, if the root cause of the problem is not identified and corrected, your problem will remain!

For more information visit:

www.holsetaftermarket.com

